

## Stormwater Utility Division – Grape Street Detention Pond



Initial cuts on detention pond (notice 18' of silt layer at top of picture).



Initial stockpile of sediment to be removed. Several additional cuts were performed later to get the detention pond back to original specifications.



Graded detention pond ready for additional cuts.