

Stormwater Utility Division – Elm Creek; west of North Winters Freeway



Debris accumulation in Elm Creek at Winters Freeway - north. (January 2009)



Standing water and debris in Elm Creek at Winters Freeway - north. (January 2009)



Debris and silt removed from under bridge to remove standing water. (February 2009)



Stormwater preparing to remove final silt to release water standing on east side of Winters Freeway Bridge. Approximately 2 feet of silt removed. (February 2009)



Water flowing through previously blocked drainage way under north Winters Freeway Bridge.
(March 2009)